



Falmouth Harbour
Commissioners

PORT NOTICE TO MARINERS

NO. 8 OF 2010

The Governor Buoy – East Cardinal Mark

NOTICE IS HEREBY GIVEN that

The Governor East Cardinal pillar buoy in position $50^{\circ} 09.152'N$ $005^{\circ} 02.401' W$ is missing the top mark. Light characteristic VQ (3) 5 s and the main body of the mark are unaffected.

This notice is self cancelling on restoration of the top mark.

**HARBOUR OFFICE
FALMOUTH
TR11 3JQ**

**M J SANSOM
HARBOUR MASTER
07th July 2010**