



Falmouth Harbour
Commissioners

PORT NOTICE TO MARINERS

NO. 2 OF 2010

Tidal Data Survey

NOTICE IS HEREBY GIVEN that a tidal monitoring buoy is located on the site of the Admiralty Tidal Diamond “B” (Chart 32) approximately 250m NE of the Eastern Breakwater Light in Lat 50° 09.46 Long 05° 02.76 (WGS 84). The buoy is small and yellow and has a stainless steel superstructure. It is lit with a Flashing Amber Light Fl 4s. The buoy is expected to be on station for approximately 30 days.

Port Notice No 7 of 2009 is hereby cancelled.

**HARBOUR OFFICE
FALMOUTH
TR11 3JQ**

**M J SANSOM
HARBOUR MASTER
5th March 2010**