



Falmouth Harbour  
Commissioners

**PORT NOTICE TO MARINERS**

**NO. 3 of 2012**

**NOTICE IS HEREBY GIVEN** that the data buoy, a yellow special mark lit with the character Fl (5) Y 20s located in position 50 deg 04.75N 005 deg 02.85W has been temporarily removed from station. It is expected that the data buoy will be re-positioned during March 2012.

Mariners are advised not to anchor or conduct seabed operations in the vicinity due to obstructions on the seabed at the above position.

This notice is self cancelling on reinstatement of the data buoy.

**HARBOUR OFFICE  
FALMOUTH  
TR11 3JQ**

**M J SANSOM  
HARBOUR MASTER**

**30<sup>th</sup> January 2012**